

INTRODUCTION


Carlisle Interconnect Technologies (CarlisleIT) is pleased to offer turnkey integration kits for the SmartSky 4G LTE ATG system. These kits are ideal for all installations where customized engineering is expensive and unnecessary.

Coax and harness kits are engineered to custom cabling lengths and connectors to match your installation needs. The ABR tray is manufactured per ARINC 404A, 3/8 ATR specifications. CarlisleIT's engineering team is available to answer questions and provide guidance on selecting the perfect combination of components for your specific application.

FEATURES	BENEFITS	
Coax Cable Kits	Custom lengthsFully and partially terminated coaxial cable assembliesStandard and waterproof options	
3/8 ATR Tray	 Designed and qualified per ABR specifications 	
Harness Kits	Custom lengthsPartially terminated P1 and P2 harnessesFDQ and HPB loose parts kits to complete installation	

TRAY

The tray (P/N: 200-106007-101) is designed per ARINC 404A, 3/8 ATR specifications and is equipped with rear guide pins and front hold-downs to properly secure the ABR LRU. Additional custom options are available upon request. Contact CarlisleIT engineering to confirm the right tray for your application.



COAX KITS


Standard Coax Kits

Standard coaxial cable kits are engineered to your required length and optimized for loss and attenuation dependent upon your installation length. Various connectors (straight or right-angled) and cable types are available to optimize your installation needs. The kits are designed for both fully terminated and partially terminated options. Just plug and play!

Please refer to the configurator worksheet and linked drawing to generate your coax P/N. TNC coax connectors are automatically chosen based on cable type and connector configuration.

Example Configuration P/N: 500-106379-1602A/3207B

- FDQ Cable Length = 160"
- FDQ Cable Type = P/N: 311901 = 2
- FDQ TNC Connector Configuration = Straight (TXB1, RXB1), Straight (TX, RX) = A
- HPB Cable Length = 320"
- HPB Cable Type = P/N: 311201 = 7
- HPB TNC Connector Configuration = Straight (RXW1, RXW2, RXW3, RDW4), Right Angle (RX1, RX2, RX3, GPS) = B



SmartSky Coax Installation Example kit P/N: 500-106379-1602A/3207B

Waterproof Kits

In addition to our standard coaxial cable kits, CarlisleIT is pleased to offer a waterproof coaxial cable kit option. The waterproof kits include our standard 311201 50 Ω cable, along with our CTSW122 TNC connectors. The cables are engineered to your required length.

Please refer to the configurator worksheet and linked drawing to generate your Coax P/N.

Example Configuration P/N: 500-106380-160/320


- TXB1/TX 500-106380-160-01 160", Cable Type 311201, CTSW122 Connectors
- RXB1/RX 500-106380-160-02 160", Cable Type 311201, CTSW122 Connectors
- RXW1/RX1 500-106380-320-03 320", Cable Type 311201, CTSW122 Connectors
- RXW2/RX2 500-106380-320-04 320", Cable Type 311201, CTSW122 Connectors
- RXW3/RX3 500-106380-320-05 320", Cable Type 311201, CTSW122 Connectors
- RXW4/GPS 500-106380-320-06 320", Cable Type 311201, CTSW122 Connectors

HARNESS KITS


Connector harness kits are engineered to your desired lengths per aircraft bus location and antenna specified in the installation manual. Please refer to the following worksheets to build your P1 and P2 harnesses.

All harnesses are terminated at the connector end and capped at the A/C end. Ethernet, databus, USB, and discrete wires specified in the installation manual are used to populate the connector harnesses. The harnesses also include the mating backshells for P1 and P2. In addition to the P1 and P2 kits, a loose parts kit has been designed to complete the installation.

Additional bulk wire and cable can be purchased separately from the harnesses to accommodate additional Ethernet and databus connections.



SmartSky P1 Harness Example P/N: 600-106578-132/064/168/302



SmartSky P2 Harness Example P/N: 600-106579-132/064/168/302

SmartSky 4G LTE ATG FDQ & HPB Standard Coaxial Configurator Worksheet

INSTRUCTIONS

1) Complete as many questions as possible on the following form.

2) Email a copy of this form to **Sales@CarlislelT.com** or fax a copy to 414.421.5301. Call CarlisleIT Customer Service with any questions 800.327.9473 (USA) or 414.421.5300 (INTL).

Contact Name:	Order Date:	Purchase Order Number:
Company:	Date Needed:	Quantity:
Telephone:	Fax:	Email:

STANDARD PART NUMBER GUIDE FOR FDQ & HPB COAX KITS

Fill in part number below					
500-106379-					
		- HPI	B Connector	Co	onfiguration
			aight, Straight		Straight, Straight (One End Terminated)
		B Str	raight, Right Angle	Е	Straight, Right Angle (Straight End Terminated)
		B Rig	ght Angle, Straight	E	Right Angle, Straight (Straight End Terminated)
		C Ri	ght Angle, Right Ang	le F	Right Angle, Right Angle (One End Terminated)
		= HPI	B Cable Typ	6	
		0	432101	5	311501
		1	352001	6	421201
		2	311901	7	311201
		3	421601	. 8	310801
		4	311601	9	310701
			ater Length>	· Co	onfiguration
			raight, Straight		Straight, Straight (One End Terminated)
			raight, Right Angle		Straight, Right Angle (Straight End Terminated)
			ght Angle, Straight		Right Angle, Straight (Straight End Terminated)
		C Ri	ght Angle, Right Ang	le F	Right Angle, Right Angle (One End Terminated)
		= FDC	Cable Typ	е	
		0	432101	5	311501
		1	352001	6	421201
		2	311901	7	311201
		3	421601	8	310801
		4	311601	9	310701
		_ FDC	Q Cable Len	gth	(in)
	i		ter Lenath >	-	

FDQ & HPB Waterproof Coaxial Configurator Worksheet

INSTRUCTIONS

1) Complete as many questions as possible on the following form.

 Email a copy of this form to Sales@CarlislelT.com, or fax a copy to 414.421.5301. Call CarlisleIT Customer Service with any questions 800.327.9473 (USA) or 414.421.5300 (INTL).

Contact Name:	Order Date:	Purchase Order Number:
Company:	Date Needed:	Quantity:
Telephone:	Fax:	Email:

WATERPROOF PART NUMBER GUIDE FOR FDQ & HPB COAX KITS

Fill in part number below

500-106380-	
	HPB Cable Length (in) <enter length=""></enter>
	FDQ Cable Length (in) <enter length=""></enter>

P1 Harness Configurator Worksheet


INSTRUCTIONS

1) Complete as many questions as possible on the following form.

 Email a copy of this form to Sales@CarlislelT.com or fax a copy to 414.421.5301. Call CarlisleIT Customer Service with any questions 800.327.9473 (USA) or 414.421.5300 (INTL).

Contact Name:	Order Date:	Purchase Order Number:
Company:	Date Needed:	Quantity:
Telephone:	Fax:	Email:

STANDARD PART NUMBER GUIDE FOR P1 HARNESS KITS



P2 Harness Configurator Worksheet


INSTRUCTIONS

1) Complete as many questions as possible on the following form.

 Email a copy of this form to Sales@CarlislelT.com or fax a copy to 414.421.5301. Call CarlisleIT Customer Service with any questions 800.327.9473 (USA) or 414.421.5300 (INTL).


Contact Name:	Order Date:	Purchase Order Number:
Company:	Date Needed:	Quantity:
Telephone:	Fax:	Email:

STANDARD PART NUMBER GUIDE FOR P2 HARNESS KITS



Global Manufacturing. Local Support.

Wherever you are, so are we. With manufacturing centers around the globe, our highly qualified team of engineers is up to any challenge. Our extensive worldwide manufacturing capabilities, coupled with end-to-end local project management and engineering support, allow us to design, build, test, and certify your product in-house, saving you the time and hassle of managing multiple vendors.



Performance with Purpose



See CarlisleIT's full line of products at: CarlisleIT.com/products +1 (800) 458-9960 Sales@CarlisleIT.com